

FIG. 1

1/8




FIG. 1
(RELATED ART)

2/8




FIG. 2A




FIG. 2B




FIG. 3A




FIG. 3B




FIG. 4A




FIG. 4B




FIG. 5

FIG. 2A

3/8




FIG. 6




FIG. 7

FIG. 6




FIG. 8

5/8

FIG. 9A




FIG. 9A





FIG. 9B

7/8



A6	A5	A4	LATENCY
0	0	1	1
0	1	0	2
0	1	1	3

FIG. 11




FIG. 12

FIG. 10 (RELATED ART)

8/8




FIG. 13A




FIG. 13B




FIG. 14

004504 0001 100E80 12054660